



The QuickField Portable Workstation Kit is the ideal all-in-one solution for fusion splicing and field prep work. Designed for maximum portability, stability, and user comfort, this kit includes the Tray with padded waist plate, PWS-S3 Neck Strap, and PWS-T65 Telescoping Tripod, making it perfect for any jobsite.

- The QuickField Tray with 7 carefully designed compartments to hold all essential splicing tools, including custom-molded slots for the FDC-66 and FD-200.
- Slots for securely mounting Jonard's SPARC Fusion Splicers or most fusion splicer models on the market up to 9.5" wide and 12" long.
- Versatile mounting options: wearable with a neck strap and waist plate or mountable on the PWS-65 telescoping tripod.
- Both the neck strap and waist plate are padded to reduce strain in the field.
- The PWS-65 tripod extends from 26.5" up to 65", allowing you to work at the height you prefer, whether sitting or standing.
- Modular drawstring carrying cases that fit all components with the option to remove tripod and carry it separately.

SPECIFICATIONS			
UNIT OF MEASUREMENT	Metric & Imperial		
TRAY COMPARTMENT DIMENSIONS	Large Rectangular Comp.: 9.5" W x 12" L		Small Rectangular Comp.: 3.5" W x 5.75" L
	Large Round Comp.: 2.5" Diam.		Small Round Comp.: 2" Diam.
TRIPOD THREAD	3/8" x 16		
TRIPOD HEIGHT	Shortest Height: 26.5" / Extended Height: 65"		
STRAP LENGTH	55"		
STRAP WIDTH	3"		
DIMENSIONS	n/a		
WEIGHT	n/a		
UPC #	810132439360		

